

Inspection Photos
Operator: BP America
API: 067-06962
Date: 8/25/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass and irrigated sedges/rushes.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area comprised of ponderosa pine and gambel oak woodland with grasses such as squirreltail, western wheatgrass, and smooth brome and purple asters in the understory.