

Inspection Photos
Operator: BP America
API: 067-07174
Date: 8/25/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern cut-slope. Erosion control blanket installed along the slope.



Photo 3. View of the southern project area from the southeastern project area facing westward. Revegetation is progressing with smooth brome, western wheatgrass, and sand dropseed.



Photo 4. View of reference area comprised of ponderosa pine woodland with understory of gambel oak, Sandberg bluegrass, and forbs such as purple aster.