

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2020

Submitted Date:

08/26/2020

Document Number:

700701419

**FIELD INSPECTION FORM**Loc ID 334938 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                     | Comment |
|--------------|-------|---|---------|
| , Caerus     |       | COGCC.inspections@caerus<br>oilandgas.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 261411      | WELL | PR     | 05/28/2004  | GW         | 045-07954 | SHIDELER 25-2A1 (B25W) | PR          |
| 261412      | WELL | PR     | 05/28/2004  | GW         | 045-07955 | SHIDELER 25-2A(B25W)   | PR          |
| 266198      | WELL | PR     | 05/28/2004  | GW         | 045-09129 | SHIDELER 25-2C (B25W)  | PR          |
| 267578      | WELL | PR     | 04/26/2004  | GW         | 045-09200 | SHIDELER 25-7 (B25W)   | PR          |
| 267583      | WELL | PR     | 10/07/2003  | GW         | 045-09203 | SHIDELER 25-1 (B25W)   | PR          |
| 267584      | WELL | PR     | 05/28/2004  | GW         | 045-09204 | SHIDELER 25-2D (B25W)  | PR          |

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 8/26/20 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus B25, at Location # 334938 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

This is a summary of inspection report.

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action | L      | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Comment:           | 911 |       |  |
| Corrective Action: |     | Date: |  |

**Good Housekeeping:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | DEBRIS |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                                   |  |  |  |                 |
|-----------------------------------|--|--|--|-----------------|
| <b>Equipment:</b>                 |  |  |  | corrective date |
| Type: Vertical Heated Separator   | # 5  |  |  |                 |
| Comment:                          |  |  |  |                 |
| Corrective Action:                |  |  |  | Date:           |
| Type: Plunger Lift                | # 7  |  |  |                 |
| Comment:                          |  |  |  |                 |
| Corrective Action:                |  |  |  | Date:           |
| Type: Bird Protectors             | # 3  |  |  |                 |
| Comment:                          |  |  |  |                 |
| Corrective Action:                |  |  |  | Date:           |
| Type: Deadman # & Marked          | # 4  |  |  |                 |
| Comment:                          |  |  |  |                 |
| Corrective Action:                |  |  |  | Date:           |
| Type: Ancillary equipment         | # 1  |  |  |                 |
| Comment:                          | 500 gallon methanol tank in tank battery         |  |  |                 |
| Corrective Action:                |  |  |  | Date:           |
| Type: Horizontal Heated Separator | # 2  |  |  |                 |
| Comment:                          |  |  |  |                 |
| Corrective Action:                |  |  |  | Date:           |
| Type: Gas Meter Run               | # 8  |  |  |                 |
| Comment:                          | All meters calibrated on location within a year. |  |  |                 |
| Corrective Action:                |  |  |  | Date:           |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 3 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     | Date:               |             |

**Venting:**

|        |    |  |
|--------|----|--|
| Yes/No | NO |  |
|--------|----|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities  |           |       |      |             |           |         |    |               |    |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 261411    | Type: | WELL | API Number: | 045-07954 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 261412    | Type: | WELL | API Number: | 045-07955 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 266198    | Type: | WELL | API Number: | 045-09129 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 267578    | Type: | WELL | API Number: | 045-09200 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 267583    | Type: | WELL | API Number: | 045-09203 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 267584    | Type: | WELL | API Number: | 045-09204 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |           |       |      |             |           |         |    |               |    |
| Comment:              | producing |       |      |             |           |         |    |               |    |
| Corrective Action:    |           |       |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 | Culverts                |                       |               |                          |         |
| Gravel           |                 | Gravel                  |                       |               |                          |         |
| Ditches          |                 | Ditches                 |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 700701425    | photo logs  | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5232837">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5232837</a> |