

Inspection Photos

Location Name: LARAMIE ENERGY LLC Woods Spangler /15-13 Pad

Location ID: 334499



Photo #1796 from entrance to location



Photo #1797 from entrance to location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Woods Spangler /15-13 Pad

Location ID: 334499



Network time is not synchronize
Local: Mar 24, 2020 at 1:46:22 PM MDT
+39.2697, -107.877

Photo #0815 from inspection #699800778 conducted on 3/24/20.



Network: May 27, 2020 at 11:48:06 AM MDT
Local: May 27, 2020 at 11:48:06 AM MDT
+39.2705, -107.877

Photo #1264 from inspection #699801170 conducted on 5/27/20.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Woods Spangler /15-13 Pad

Location ID: 334499



Photo #1798 Unused pipe stored on North end of location.