

BP L48 San Juan



V2 Compliance Follow Up Form

18152971334

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200826-18152971334

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Aug 26, 2020 10:59:26 AM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Aug 26, 2020 10:59:15 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name	colen@horizonenvservices.com
Date	Aug 25, 2020
Well Name	RICHARDSON GAS UNIT 01-25 1
API Number	50670650700
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Photo of first corrective action completed	



**Completed work description Corrective
Action 1**

Removed thistle heads and treated thistle
populations.

Photo of second corrective action completed



Completed work description of corrective action 2

Photo of third corrective action completed

Removed weed species treated thistle populations.



Completed work description of corrective action 3

Seed heads removed.

Photo of fourth corrective action completed



Completed work description

Treated thistle population.

Completed work description of corrective action 4

Treated thistle population.

Additional photos



Additional photos

**Completed work description**

Removed thistle heads and selectively treated thistle populations.

Summary of all work completed

Previous treatment dates 7/21/2016, 7/13/2017, 7/10/2018, 6/25/2019