

BP L48 San Juan



V2 Compliance Follow Up Form

18152888975

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200825-18152888975

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Aug 25, 2020 4:38:24 PM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Aug 25, 2020 4:37:37 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Aug 25, 2020

Well Name

STATE 01-36, 35-08 2

API Number

50670715800

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Clean Up Weed Debris

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

Before removing seed heads and spraying.

Photo of second corrective action completed



Completed work description of corrective action 2

Before removing seed heads and spraying.

Photo of third corrective action completed



Completed work description of corrective action 3

Photo of fourth corrective action completed

Removed thistle heads and treated thistle population.



Completed work description

Treated thistle population.

Completed work description of corrective action 4

Treated thistle populations.

Additional photos



Additional photos

**Completed work description**

Removed thistle heads, treated thistle populations.

Summary of all work completed

Removed thistle heads and treated thistle population. Previous treatment dates 7/13/2017, 7/10/2018, 6/27/2019