

Inspection Photos

Location Name: RGU 11-25-198 PAD

Location ID: 335671 & Spill/Release ID: 477610

Inspection Date: August 7, 2020



Location sign.



Tank battery looking southeast.

Inspection Photos

Location Name: RGU 11-25-198 PAD

Location ID: 335671 & Spill/Release ID: 477610

Inspection Date: August 7, 2020



Impacted material located on the exterior of the tank battery.



Impacted material within the tank battery secondary containment structure.



Inspection Photos

Location Name: RGU 11-25-198 PAD

Location ID: 335671 & Spill/Release ID: 477610

Inspection Date: August 7, 2020



Residual staining ring and patches peeling off the synthetic liner.



Residual staining ring and patch peeling off the synthetic liner.



Inspection Photos

Location Name: RGU 11-25-198 PAD

Location ID: 335671 & Spill/Release ID: 477610

Inspection Date: August 7, 2020



Patch peeling off the synthetic liner.



Patch peeling off the synthetic liner.



Inspection Photos

Location Name: RGU 11-25-198 PAD

Location ID: 335671 & Spill/Release ID: 477610

Inspection Date: August 7, 2020



Impacted material within the tank battery secondary containment structure.



Northwest corner of the tank battery, note the patch peeling off and the missing patch (red area).

