

Inspection Photos

Location#334960

Operator: Caerus

Inspection #: 692402343

Inspection Date: 8/23/20





Photo#1:
Overview of Location to East.

August 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Location#334960



Photo#2:
Subsidence repaired.



Photo#3:
View over interim area.

August 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Location#334960