

**Inspection Photos**  
**Operator: BP America**  
**API: 067-07264**  
**Date: 8/18/2020**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and intermediate wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of sagebrush shrubland and pinyon/juniper woodland vegetation with grasses such as James galleta, blue grama, needleandthread grass and forbs such as *Heterotheca villosa* and Townsend daisy.