

Inspection Photos
Location Name: Airco #2
API: 05-083-06536



Airco #2 well head and location sign.



Eastern soil stockpile.

Inspection Photos
Location Name: Airco #2
API: 05-083-06536



Western soil stockpile.



Excavated area resulting from Spill/Release Point ID #458267.

Inspection Photos
Location Name: Airco #2
API: 05-083-06536



55 gal. drum on secondary containment.



Airco #2 production equipment and open excavation.