

## Inspection Photos

Location Name: HOWARD USX A-66N64W /9SWSW

Location #: 306348



**Photo #1**

**Howard USX A 9-13 (05-123-24494) Wellsite**

**Shut-In | SI**

**Weeds**



**Photo #2**

**Howard USX A 9-13 Battery site**

**Inactive | Shut-down**