

Pit Status Evaluation Form

Pit Overview:

Pit Name: SELTZER A-1	Facility ID: 118538
Current Status: Unknown	Status Date: 9/23/1999
Current Operator:	
Updated Operator: VESSELS OIL & GAS COMPANY / 93200	
Form 15 Pit Permit Doc #: 383015	Permit Date: 12/17/1976
Related Facilities: SELTZER #1-A (API 123-08471 Facility ID 240683; Loc ID 311297)	

County: WELD			
Township: 1N	Range: 67W	Section: 34	QQ: NWSW
Original Latitude/ Longitude: 40.005799 / -104.883622			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date: 07/23/2020	Document #: 689501077
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
No evidence of a pit on location. Produced water goes to a fiberglass tank.	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 383015 | Date: 12/17/1976 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 50784 | Date: 6/26/1996 |
| | Doc #: 816522 | Date: 10/14/1999 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location.

Pit Status Review Summary:

Based on records review and aerial imagery, any pits on location were removed prior to the 6/26/1996 field inspection. Field inspection (doc 689501077) found no evidence of a pit on location - produced water on location goes to a cement tank. Pit status has been changed to closed.

