

Pit Status Evaluation Form

Pit Overview:

Pit Name: AUGUST GITTLEIN 1	Facility ID: 118161
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #: 383015	Permit Date: 2/16/1973
Related Facilities: SELTZER #1-A (API 123-08471 Facility ID 240683; Loc ID 311297)	

County: WELD

Township: 1N	Range: 67W	Section: 3	QQ: NENW
---------------------	-------------------	-------------------	-----------------

Original Latitude/ Longitude: 40.085528 / -104.879402

Updated Latitude/ Longitude: 40.085306 / -104.877208

Basis for Location Change:

Location updated based on pit permit and aerial imagery

Pit Inspection/Information Request:

Field Inspection Date: 07/23/2020	Document #: 689501079
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
No evidence of a pit on location. Produced water goes to a tank.	
This tank battery serves multiple wells in the area - see inspection photos for a list of wells served.	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 383015 | Date: 2/16/1973 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 30903 | Date: 1/30/1996 |
| Doc #: 816522 | Date: 10/14/1999 |
| Doc #: | Date: |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Any pits on location were removed prior to the 1996 field inspection.

Pit Status Review Summary:

Based on records review and aerial imagery, the pit on location was replaced with a tank prior to the 1/30/1996 field inspection. Field inspection (doc 689501079) found no evidence of a pit on location - produced water on location goes to a tank located at the former pit location. Pit status has been changed to closed, however, no associated remediation or site investigation has been conducted. Should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required.



