

Inspection Photos
Location Name: HOWARD USX A /09-19
Location #: 423200



Colorado Oil & Gas Conservation Commission
40.50396, -104.56012, 4806.4ft, 10°
08/28/2020 15:04:53

Photo #1

Howard USX A /09-19 4: Wellsites
3: Temporarily Abandoned | TA
1: Plugged & Abandoned | PA



Colorado Oil & Gas Conservation Commission
40.50488, -104.56318, 4783.7ft, 170°
08/28/2020 15:49:24

Photo #2

Howard USX A 09-19, 09-12D, 09-6D Battery site
Inactive | Shut-down
Formerly served:
Howard USX A 09-02D
Plugged & Abandoned | PA

Inspection Photos
Location Name: HOWARD USX A /09-19
Location #: 423200



Photo #3

Howard USX A 09-19 (05-123-33520) Wellsite
Temporarily Abandoned | TA
Weeds



Photo #4

Howard USX A 09-12D (05-123-33531) Wellsite
Temporarily Abandoned | TA
Weeds

Inspection Photos
Location Name: HOWARD USX A /09-19
Location #: 423200



Photo #5

Howard USX A 09-06D (05-123-33532) Wellsite
Temporarily Abandoned | TA
Weeds



Photo #6

Howard USX A 09-02D (05-123-33521) Wellsite
Plugged & Abandoned | PA
~ 5 yds.