

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2020

Submitted Date:

08/31/2020

Document Number:

696103631**FIELD INSPECTION FORM**Loc ID: 423200 Inspector Name: Evins, Bret On-Site Inspection: ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423186	WELL	TA	03/23/2020	OW	123-33521	HOWARD USX A 09-02D	PA

**General Comment:**This is a **PLUGGED & ABANDONED WELL** inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Battery: Inactive | Shut-down.

Refer to Field Inspection Report doc. #696103629 and/or Location ID #423200  
for Battery / Facility, Equipment info.

**Inspected Facilities**

Facility ID: 423186 Type: WELL API Number: 123-33521 Status: TA Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 08/28/2020 at approximately 15:11 hrs. I, Bret Evins, conducted an on-site inspection at:            Operator Name: NOBLE ENERGY INC            Location Name: HOWARD USX A /09-19            Location ID: 423200            Well Name: Howard USX A 09-02D            API: 05-123-33521            Location County: Weld County, Colorado            Weather: Mostly cloudy, dry.</p> <p>While there, I observed:            Well(s): 1: Plugged &amp; Abandoned   PA.            Battery: Inactive   Shut-down.</p> <p>Refer to Field Inspection Report doc. #696103629 and/or Location ID #423200 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT:            Plugged &amp; Abandoned   PA.            Well appears to be cut / capped.            Form 6 doc. #402347884 indicates plugging, cut/cap date: 12/19/2019. Approval Pending.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/31/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103632	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5235851">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5235851</a>