

Final Reclamation Inspection

August 26, 2020

Operator: WARD PETROLEUM CORPORATION- #10359

Location ID: 330647

Inspection Document #: 697501949

Weld County, CO

NENW Section 23 T10N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: UPRC FEDERAL #23-2
Location ID: 330368



Photo 1. Photo taken from the western access road, facing East. Photo illustrates the access road has not been reclaimed and does not meet Rule 1004 vegetative requirements.

Note: Forest Service indicated continued use.

Inspection Photos
Location Name: UPRC FEDERAL #23-2
Location ID: 330368



Photo 2. Photo taken from the central access road, facing West. See comments under Photo 1.

Inspection Photos
Location Name: UPRC FEDERAL #23-2
Location ID: 330368



Photo 3. Photo taken from the central access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: UPRC FEDERAL #23-2
Location ID: 330368



Photo 4. Photo taken from the well location, facing Southeast. Photo illustrate vegetative levels are reflective of reference areas.

Inspection Photos
Location Name: UPRC FEDERAL #23-2
Location ID: 330368



Photo 5. Photo taken from the well location, facing South. See comments under Photo 4.

Inspection Photos
Location Name: UPRC FEDERAL #23-2
Location ID: 330368



Photo 6. Reference photo taken north of the well location, facing North. See comments under Photo 4.

Inspection Photos
Location Name: UPRC FEDERAL #23-2
Location ID: 330368



Photo 7. Photo taken from the associated offsite tank battery location, facing East. Photo illustrates the tank battery is still in use and operated by HighPoint.