

Inspection Photos  
Location Name: Dehaan V 27-10  
Location ID: 336241



Photo 1 WH sign

Photo 2 WH

Inspection Photos  
Location Name: Dehaan V 27-10  
Location ID: 336241




Photo 3 TB sign

Photo 4 TB

Inspection Photos  
Location Name: Dehaan V 27-10  
Location ID: 336241



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 5 Gas Meter Run

Photo 6 Card in meter house does not indicate current calibration

**Inspection Photos**  
**Location Name: Dehaan V 27-10**  
**Location ID: 336241**



**Photo 7 Horizontal Heated Separator**

**Photo 8 ECD**