

Inspection Photos
Location Name: Martin T. Hart #2
Location ID: 318464



Photo 1 WH sign faded operator and emergency contact information not legible.



Photo 2 WH

Inspection Photos
Location Name: Martin T. Hart #2
Location ID: 318464



Photo 3 Pump Jack not in use.



Photo 4 unused equipment, Pump Jack belts free no motor



Inspection Photos
Location Name: Martin T. Hart #2
Location ID: 318464



Photo 5 unused electric wire from electric panel.



Photo 6 unused equipment, Pump Jack has no electric motor attached to it.

Inspection Photos
Location Name: Martin T. Hart #2
Location ID: 318464



Photo 7 unused meter box and transformers no motor to power up.