

Inspection Photos
Location Name: HILL RANCH 06-04
API#: 05-071-07432
INSP. #: 695103250



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos

Location Name: HILL RANCH 06-04

API#: 05-071-07432

INSP. #: 695103250



PHOTO 3: TRASH IN EARTH PIT. REMOVE REMINENCE OF PIT LINER THAT WAS LEFT AFTER REMOVING PIT LINER, COMPLY WITH RULE 603.f. CA DATE 9-8-20.

PHOTO 4: IMAGE OF MORE TRASH IN EARTH PIT.