

Inspection Photos
Location Name: HILL RANCH 31-14
API#: 05-071-09567
INSP. #: 695103252



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: HILL RANCH 31-14
API#: 05-071-09567
INSP. #: 695103252



PHOTO 3: TRASH IN EARTH PIT (PIECES OF PIT LINER LEFT IN PIT). REMOVE ALL TRASH IN AND AROUND PIT, COMPLY WITH RULE 603.f. CA DATE 9-8-20.



PHOTO 4: MORE IMAGES OF PIT LINER ON TOP EDGE OF PIT. REMOVE ALL TRASH IN AND AROUND PIT, COMPLY WITH RULE 603.f. CA DATE 9-8-20.

Inspection Photos

Location Name: HILL RANCH 31-14

API#: 05-071-09567

INSP. #: 695103252



**PHOTO 5: MORE IMAGES OF PIT LINER ON TOP EDGE OF PIT.
REMOVE ALL TRASH IN AND AROUND PIT, COMPLY WITH
RULE 603.f. CA DATE 9-8-20.**



**PHOTO 6: NOXIOUS WEED NEAR ENTRANCE OF LOCATION.
CONTROL WEEDS.**