

Inspection Photos
Location Name: AP 09-07
API#: 05-071-06190
INSP. #: 695103254



Colorado Oil & Gas Conservation Commission
37.21025, -105.04643, 153°
2020/08/25 12:20:52

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.1017, -104.99836, 2645.0m, 304°
2020/08/25 12:21:03

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: AP 09-07
API#: 05-071-06190
INSP. #: 695103254



**PHOTO 3: UNMARKED UNUSED RISERS ON NORTHWEST
EDGE OF LOCATION. REMOVE OR MARK RISERS, COMPLY
WITH RULE 603.f. CA DATE 11-26-20.**

