

Inspection Photos  
Location Name: APACHE CANYON 10-01  
API#: 05-071-08277  
INSP. #: 695103256



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



## Inspection Photos

Location Name: APACHE CANYON 10-01

API#: 05-071-08277

INSP. #: 695103256



**PHOTO 3: UNMARKED UNUSED RISERS NOT LO/TO. REMOVE OR MARK AND LOCKOUT/TAGOUT RISERS, COMPLY WITH RULE 603.f. CA DATE 11-25-20.**



**PHOTO 4: UNMARKED UNUSED RISERS NOT LO/TO. REMOVE OR MARK AND LOCKOUT/TAGOUT RISERS, COMPLY WITH RULE 603.f. CA DATE 11-25-20.**



Inspection Photos  
Location Name: APACHE CANYON 10-01  
API#: 05-071-08277  
INSP. #: 695103256



**PHOTO 5: TRASH/DEBREE ON WEST SIDE OF LOCATION.**  
**REMOVE ALL TRASH ON AND AROUND LOCATION, COMPLY**  
**WITH RULE 603.f. CA DATE 11-25-20.**



**PHOTO 6: IMPACTED SOIL NEAR COMPRESSOR INSIDE**  
**SOUNDWALLS. "Properly dispose of oily waste in accordance**  
**with 907.e." CA DATE 11-25-20.**




## Inspection Photos

Location Name: APACHE CANYON 10-01

API#: 05-071-08277

INSP. #: 695103256



**PHOTO 7: NOXIOUS WEEDS ON EDGE OF LOCATION AND ON INTERIM RECLAMATION AREA ALSO ALL ALONG THE ROW GOING TO THE WEST OF LOCATION. **CONTROL WEEDS.****

**PHOTO 8: MORE IMAGES OF NOXIOUS WEEDS.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: APACHE CANYON 10-01

API#: 05-071-08277

INSP. #: 695103256



**PHOTO 9: NOXIOUS WEEDS NORTH OF LOCATION.**