

Inspection Photos
Location Name: AC 02-13
API#: 05-071-06124
INSP. #: 695103257



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: AC 02-13
API#: 05-071-06124
INSP. #: 695103257



PHOTO 3: NOXIOUS WEEDS NEAR WEST ENTRANCE TO LOCATION. CONTROL WEEDS.



PHOTO 4: NOXIOUS WEEDS NEAR WEST ENTRANCE TO LOCATION. CONTROL WEEDS.

Inspection Photos
Location Name: AC 02-13
API#: 05-071-06124
INSP. #: 695103257



PHOTO 5: AREA OF IMPACTED SOIL AROUND COMPRESSOR.

"Properly dispose of oily waste in accordance with 907.e."
CA DATE 11-25-20.