

Inspection Photos  
Location Name: NGL C9B  
Location ID: 440284




Photo 1 – Wellhead, Stained Soil




Photo 2 – Wellhead, Stained Soil

**Inspection Photos**  
**Location Name: NGL C9B**  
**Location ID: 440284**



**Photo 3 – Wellhead Sign**