

Inspection Photos

Location Name: LARAMIE ENERGY LLC Mesa /18-2 Pad

Location ID: 312636



Photo #1816 from entrance to location



Photo #1817 Containment by pig station full of oily fluids.