

Inspection Photos

API: 071-09033

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/31/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 1. Facing southwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 2. Facing west along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 3. There are areas along the cut slope that are not stabilized.



Inspection Photos



Photo 4. Facing north along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 5. Facing northeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 6. Facing toward the cut slope. The vegetation has not adequately established along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 7. Standing at the top of the cut slope facing southwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 8. Facing west standing at the top of the cut slope. The vegetation has not adequately established along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 9. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 10. Facing east toward the cut slope. The vegetation has not adequately established along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 11. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 12. Facing west of the fill slope. The vegetation has not adequately established along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020

Inspection Photos



Photo 13. Facing toward the surrounding undisturbed vegetation which consists of Little bluestem, Blue grama, Mtn Muhly, Sand dropseed among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09033 | Date: 8/31/2020