

# Inspection Photos

API: 071-07613

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/31/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07613 | Date: 8/31/2020

## Inspection Photos



**Photo 1.** Facing west at the beginning of the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07613 | Date: 8/31/2020

## Inspection Photos



**Photo 2.** Outlet protection is installed at the culvert.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07613 | Date: 8/31/2020

## Inspection Photos



**Photo 3.** There are rock check dams installed along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07613 | Date: 8/31/2020

## Inspection Photos



**Photo 4.** Facing west toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07613 | Date: 8/31/2020