

Inspection Photos
Location Name: Bondad 33-9 #11
API: 05-067-05474



Holes in wildlife netting.



Stained soil beneath hammer union.

Inspection Photos
Location Name: Bondad 33-9 #11
API: 05-067-05474



Bondad 33-9 #11 location photo.



Access road has ruts in it.