

Inspection Photos
Facility Name: KPK Facility 4 North
Facility ID: Spill/Release Point 477605



Oil-stained pavement where liquid hydrocarbons surfaced in westbound lane of Tipple Parkway

Oil-stained pavement where liquid hydrocarbons surfaced in westbound lane of Tipple Parkway

