

Inspection Photos
Location Name: Maudlin Gulch 26
Location ID: 312990



Photo 1. Overview of location taken facing east.

