


**Inspection Photos**  
**Location Name: Weld County Kindt 1**  
**Location ID: 327811**



**Photo 1 – Pumping Unit, Weeds at Wellhead**



**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: Weld County Kindt 1**  
**Location ID: 327811**



**Photo 3 – Wellhead Sign**



**Photo 4 – Stained Soil at Exhaust, Weeds**



**Inspection Photos**  
**Location Name: Weld County Kindt 1**  
**Location ID: 327811**



**Photo 5 – Stained Soil Gas Engine**



**Photo 6 – Stained Soil Gas Engine**

**Inspection Photos**  
**Location Name: Weld County Kindt 1**  
**Location ID: 327811**



**Photo 7 – Pit, Weeds, Cattle got into Pit Area**



**Photo 8 – Pit, Weeds, Cattle got into Pit Area. Skim Tank  
Missing Labels – Content, Capacity and NFPA**



**Inspection Photos**  
**Location Name: Weld County Kindt 1**  
**Location ID: 327811**




**Photo 9 – Berms are Tank knocked down by Cattle**




**Photo 10 – Berms are Tank knocked down by Cattle**

**Inspection Photos**  
**Location Name: Weld County Kindt 1**  
**Location ID: 327811**



**Photo 11 – Berms are Heater Treater knocked down by Cattle**



**Photo 12 – Weeds at Wellhead**