

Inspection Photos
Location Name: McCallum 176
Location ID: 324730



Photo 1. Overview of location taken facing east. Stained soil at wellhead. Wellhead sign knocked over.



Photo 2. Photo of overgrown access road.

