

Inspection Photos

8/31/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 324462

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324462



Photo 1: Photo taken from the north end of the Location, facing southeast. Photo shows desirable vegetative establishment over the Location appears uniform.



Photo 2: Photo taken from the north end of the Location, facing southwest. Photo shows desirable vegetative establishment over the Location appears uniform.