

# Inspection Photos

8/31/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 422990

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 1:** Photo taken from the Location entrance, facing south. Photo shows signage required per the Delayed IR NTO, and per COAs, has not been installed.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 2:** Photo taken from west end of the Location, facing north east. Photo provides an overview of the location.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 3:** Photo taken from west end of the Location, facing south. Photo provides an overview of the location.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 4:** Photo taken from the cut slope on the north end of the Location. Photo shows BMPs to protect and stabilize the slopes remain missing or insufficient.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 5:** Photo taken from the cut slope on the north end of the Location. Photo shows BMPs to protect and stabilize the slopes remain missing or insufficient. Erosion degradation is recurring.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 6:** Photo taken from the cut slope on the north end of the Location. Photo shows BMPs to protect and stabilize the slopes remain missing or insufficient. Erosion degradation is recurring.





Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 7:** Photo shows sediment deposition and erosion from the cutslope.





Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 8:** Photo shows bindweed establishment on the east end of the Location. This is a Colorado State listed noxious weed.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 9:** Photo shows bindweed establishment on the south end of the Location. This is a Colorado State listed noxious weed.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 10:** Photo taken from the stormwater ditch on the north end of the Location. Previous inspection observed Canada thistle establishing within ditch. Photo shows Canada thistle establishment remains evident within ditch. Previous weed management efforts appear insufficient.



## Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 422990



**Photo 11:** Photo shows Canada thistle establishment within ditch. Previous weed management efforts appear insufficient.

