

# Inspection Photos

8/31/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 414132

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 1:** Photo taken from the west end of the Location, facing northwest. Photo shows interim areas and stormwater ditch.





Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 2:** Photo taken from the outlet of the western stormwater ditch. Photo shows outlet/ditch has not been constructed in accordance with good engineering practices; Outlet remains insufficient to stabilize slopes and allow sediment laden-free stormwater discharge.





Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 3:** See comments under photo 2. Off-site sediment deposition evident.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 4:** See comments under photo 2.





Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 5:** Photo taken from the western stormwater ditch. Photo shows Channel incision/erosion evident. Operator has implemented rock checks/velocity check within ditch. BMP appears insufficient and has not been installed in accordance with good engineering practices.





Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 414132



**Photo 6:** Photo of rock check/velocity check within ditch. See comments under photo 5.

