

Inspection Photos

8/31/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 324491

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 324491



20200831

Photo 1: Photo of sign at well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324491



Photo 2: Photo of well and cellar. Photo shows chemicals previous observed within cellar have been removed. Photo also shows BMPs to prevent wildlife access to the cellar has not been installed per the CA.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324491



Photo 3: See comments under photo 3

