

BP L48 San Juan



V2 Compliance Follow Up Form

18153221445

Reference Number:	20200828-18153221445
Form Name:	V2 Compliance Follow Up Form
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) kenneth.canterbury@crossfire-llc.com
Submission Date:	Aug 28, 2020 11:37:56 AM MDT
Location:	4862 US-550, Durango, CO 81303, USA Aug 28, 2020 11:30:54 AM MDT [View Map]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 26, 2020
Well Name	MOORE, DJ GAS UNIT A 1
API Number	50670763400
Location API (Other)	MOORE , DJ Gas UNIT A2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Erosion Repairs Other Install Rock Run Down Clean up Operator Debris Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Installed rock run down

Photo of third corrective action completed



Completed work description of corrective action 3

Cleaned up stains

Photo of fourth corrective action completed



Completed work description

Erosion repair

Completed work description of corrective action 4

Erosion repair

Additional photos



Additional photos



Summary of all work completed

Compliance, installed rock run down, cleaned up stains , picked up trash , fixed erosion and marked anchors