

BP L48 San Juan



V2 Compliance Follow Up Form

18153221446

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200828-18153221446

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 21, 2020 2:39:17 PM MDT

68 Co Rd 501, Bayfield, CO 81122, USA

Aug 21, 2020 2:37:55 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

kenneth.canterbury@crossfire-llc.com

Date

Aug 19, 2020

Well Name

LE PLATT GAS UNIT B 1

API Number

50670893100

Select State

Colorado

Work type

COGCC Inspection AR

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up stains

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Removed weeds

Photo of fourth corrective action completed



Completed work description

Installed muffler box

Completed work description of corrective action 4

Picked up trash

Summary of all work completed

Compliance, installed muffler box , picked up trash , cleaned up stains and picked up weeds