

BP L48 San Juan



V2 Compliance Follow Up Form

18153222988

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200828-18153222988

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 28, 2020 12:04:58 PM MDT

5158 US-550, Durango, CO 81303, USA

Aug 28, 2020 12:00:00 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 26, 2020
Well Name	BROWN, ROY GAS UNIT A 2
API Number	50670868900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Other Clean up Operator Debris Clean Up Weed Debris Repaired Berm Removed sediment from BMP's

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective
action 2**

Fixed berm

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Fixed erosion

Photo of fourth corrective action completed



Completed work description

Built rock run down

Completed work description of corrective action 4

Picked up trash and weeds

Additional photos



Additional photos



Additional photos



Additional photos

**Summary of all work completed**

Compliance , fixed berm, installed rock run down , fixed erosion , picked up trash , marked anchors installed and installed equipment signs