

Inspection Photos

8/31/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 324461

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324461



20200831

Photo 1: Photo of the access road; Reclamation in process.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324461



Photo 2: Photo of Musk thistle observed on access road. Evidence of spraying was observed, however weed management appears insufficient as plants were observed to be viable, noxious weed establishment has continued

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324461



Photo 3: Photo shows Musk thistle establishment on the Location.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324461



Photo 4: Photo shows Musk thistle establishment on the Location. Photo also an example of plants observed that have reached seed head maturity , and in the process of seed dispersal

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324461



Photo 5: Photo shows Musk thistle rosettes observed on the Location.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324461



Photo 6: Photo of Musk thistle observed on the Location.