

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2020

Submitted Date:

09/02/2020

Document Number:

701100318

FIELD INSPECTION FORM

Loc ID 335816 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276468	WELL	PR	07/24/2009	GW	045-10470	N. PARACHUTE EF16C21 A28B595	PR
276469	WELL	PR	06/25/2007	GW	045-10471	N. PARACHUTE EF13D A28B 595	PR
276470	WELL	PR	04/04/2007	GW	045-10472	N.PARACHUTE EF12D A28B 595	PR
276471	WELL	PR	08/20/2009	GW	045-10473	N. PARACHUTE EF16A21 A28B595	PR
277520	WELL	PR	05/31/2010	GW	045-10726	N. PARACHUTE EF16B21 A28B 59	PR
277521	WELL	PR	04/15/2010	GW	045-10725	N. PARACHUTE EF16D-21A28B595	PR
277523	WELL	PR	05/11/2006	GW	045-10723	N.PARACHUTE EF13B-DX A28B 5	PR
285048	WELL	PR	04/18/2007	GW	045-12358	N PARACHUTE EF04B A28B 595	PR
294132	WELL	PR	06/03/2010	GW	045-15264	N. PARACHUTE EF08A-28 A28B 5	PR
294133	WELL	PR	09/11/2009	GW	045-15265	N. PARACHUTE EF08C-28A28B595	PR
294134	WELL	PR	07/22/2009	GW	045-15266	N. PARACHUTE EF04C-27 A28B 5	PR
294136	WELL	PR	06/01/2010	GW	045-15267	N. PARACHUTE EF01C-28 A28B 5	PR
294137	WELL	PR	06/07/2010	GW	045-15268	N. PARACHUTE EF01A-28 A28B 5	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate

Other (Content)	
Other (Capacity) 80 bbls	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	276468	Type:	WELL	API Number:	045-10470	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	276469	Type:	WELL	API Number:	045-10471	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	276470	Type:	WELL	API Number:	045-10472	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	276471	Type:	WELL	API Number:	045-10473	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	277520	Type:	WELL	API Number:	045-10726	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	277521	Type:	WELL	API Number:	045-10725	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	277523	Type:	WELL	API Number:	045-10723	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	285048	Type:	WELL	API Number:	045-12358	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 294132	Type: WELL	API Number: 045-15264	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294133	Type: WELL	API Number: 045-15265	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294134	Type: WELL	API Number: 045-15266	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294136	Type: WELL	API Number: 045-15267	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 294137	Type: WELL	API Number: 045-15268	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Gravel	Pass			
Berms	Pass					
Compaction	Pass					
		Ditches	Pass			
		Culverts	Pass			
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701100319	Inspection 701100318 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5237992