

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2020

Submitted Date:

09/02/2020

Document Number:

699102329

**FIELD INSPECTION FORM**

Loc ID 305423 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277447	WELL	TA	05/06/2020	GW	123-22949	DECHANT D 7-23	TA

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Red "PTA" variance tag.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Adequate
Corrective Action:	
	Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 277447 Type: WELL API Number: 123-22949 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: T/A. Waiting on the cut & cap crew.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Wednesday 9/2/20 at approximately 1228hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Dechant D 7-23 of Noble Energy at Location ID: 305423 in Weld County, Colorado.                      Weather: Sunny and Dry.                      While there, I observed a well that is T/A, with red "PTA" variance tag.                      No violation of the COGCC rules were observed at the time of inspection.                      This is a summary of inspection report.</p>	burnsa	09/02/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102330	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5238117">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5238117</a>