

Inspection Photos
Location Name: Oxbow 0880 S29
Location ID: 458790



Photo 1. Overview of location taken facing northwest.



Photo 2. No NFPA diamond on tank label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources