

Inspection Photos
Operator Name: XTO Energy INC
Facility ID: 434309

Yellow Creek Compressor



Line Abandonment/New Line Installation

- Yellow line: 6 inch Compressor Suction Line
- Red line: 2 inch Compressor Dump Line
- Blue line: New 6 Inch Compressor Suction Line
- Blue dots: Below Grade
- Blue line: Above Grade



Location layout

Inspection Photos
Operator Name: XTO Energy INC
Facility ID: 434309



2" flowline abandoned in place. Threaded caps installed, Flowline cut 3' below grade

Inspection Photos
Operator Name: XTO Energy INC
Facility ID: 434309



**6" flowline plugged and Abandoned in place ,
west end of flowline. Flowline cut 3' below
grade and cap welded on**

Inspection Photos
Operator Name: XTO Energy INC
Facility ID: 434309



**6" flowline plugged and Abandoned in place ,
east end of flowline. Flowline cut 3' below
grade and cap welded on**

Inspection Photos
Operator Name: XTO Energy INC
Facility ID: 434309



**New section of 6" flowline(green Pipe) 4 hour
pressure test performed at 2,032 psi**