

Inspection Photos
Location Name: Stromquist 22-21
Location ID: 336214



Photo 1 WH sign



Photo 2 WH



Inspection Photos
Location Name: Stromquist 22-21
Location ID: 336214



Photo 3 TB sign



Photo 4 Gas meter run

Inspection Photos
Location Name: Stromquist 22-21
Location ID: 336214



Photo 5 Horizontal Heated Separator



Photo 6 ECD



Inspection Photos
Location Name: Stromquist 22-21
Location ID: 336214



Photo 7 TB

