

**Inspection Photos**  
**Location Name: Klaenhammer 1**  
**Location ID: 312861**



**Photo 1. Overview of location taken facing south. Annual weeds visible in photo.**



**Inspection Photos**  
**Location Name: Klaenhammer 1**  
**Location ID: 312861**



**Photo 2. Stained soil at wellhead.**



**Photo 3. Stained soil in pit.**

