

Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 8/26/2020  
All Photos taken by Kris Neidel



Photo #1. Photo looking north. Overview of Vermillion Creek.  
Spill impacted the creek channel in center of photo.



Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 8/26/2020  
All Photos taken by Kris Neidel



Photo #2 On back of channel impacted by spill. Is this the same line that failed?

Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 8/26/2020  
All Photos taken by Kris Neidel



Photo #3 Close up of spill path in vermilion creek. No hydrocarbon or obvious impact was observed.

Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 8/26/2020  
All Photos taken by Kris Neidel



Photo #4 Close up of spill path in vermillion creek. No hydrocarbon or obvious impact was observed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 8/26/2020  
All Photos taken by Kris Neidel

Photo #5 Area of creek up stream of spill location.

Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 8/26/2020  
All Photos taken by Kris Neidel



Photo #6 existing flowline. Was this flowline abandon per surface owner?

Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 8/26/2020  
All Photos taken by Kris Neidel



Photo #7 photo not in spill path. Appears that a flowline was removed.




Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 8/26/2020  
All Photos taken by Kris Neidel



Photo #8 Flowline markers southwest of the impacted part of the creek.

d Map

cription for your map.




**Inspection Photos**  
**Spill ID 463345**  
**Remediation Project 12865**  
**Inspection Date: 8/26/2020**  
**All Photos taken by Kris Neidel**

**Slide #1. Photo location data taken from camera.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Spill ID 463345  
Remediation Project 12865  
Inspection Date: 8/26/2020  
All Photos taken by Kris Neidel

Slide #2. Close up of Slide #1.