



39.8208, -108.98578, 6068.1ft, 104°
09/04/2020 03:44:00 PM




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Park Mountain 9011

API: 05-103-09775

Inspection: 700403287



39.82072, -108.98567, 6068.0ft, 22°
09/04/2020 03:44:17 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Park Mountain 9011

API: 05-103-09775

Inspection: 700403287





39.82073, -108.98529, 6084.9ft, 44°
09/04/2020 03:44:49 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

Park Mountain 9011

API: 05-103-09775

Inspection: 700403287