

Inspection Photos

API# 081-06240

Operator: GRMR

Insp#: 692402488

Insp Date: 8/27/2020





Photo#1:
View of Location to Northwest.



Photo#2:
View of Location to South.

August 27, 2020



Inspection Photos: GRMR PA Beaver-Durham API# 081-06240



Photo#3:
Curly cup gumweed, Curly dock.

August 27, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Beaver-Durham API# 081-06240



Photo#4:
Northwestern portion has heavier grass establishment.



Photo#5:
Evidence of heavy grazing and animal impact.

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Beaver-Durham API# 081-06240



Photo#6:
Debris remains on site.



Photo#7:
Debris remains on site.

August 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Beaver-Durham API# 081-06240