

Inspection Photos

API: 071-07705

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/2/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07705 | Date: 9/2/2020

Inspection Photos




Photo 1. Aerial image of the location from 2011. The western portion of the location shows the pit area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 9/2/2020

Inspection Photos



Photo 2. Facing west along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 9/2/2020

Inspection Photos



Photo 3. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 9/2/2020

Inspection Photos



Photo 4. Facing south. The photo shows sparse vegetation. It appears reseeding has occurred.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 9/2/2020

Inspection Photos



Photo 5. Facing southwest at the western portion of the location. There are areas bare of vegetation which appear to have been reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 9/2/2020

Inspection Photos



Photo 6. Facing east at the location. Much of the dark green vegetation is Kochia which is an undesirable weedy specie.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 9/2/2020

Inspection Photos



Photo 7. Facing northeast.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07705 | Date: 9/2/2020